25X1

MSD/PIC/107/59

Office of Scientific Intelligence/ Guided

28 August 1959

Missile Division

Photo Intelligence Center Military Scientific Division

Requirement No. SI/R-31/59.

The enclosed information is submitted in partial asswer to your requirement SI/R-31/59. Your requirement will be completely answered in a report soon to be published by this Center.

25X1

Enclosures (4)

Text & 3 Graphics

cc - OSI/GMD OSI/ED Atten: 25X1 PIC/CCS PIC/MSD Prej. Forber Prin-59

Referral Declassification by NIMA/DoD

ILLEGIB

Ms 0/ PIC/15\$/59

25X1

25X1

25X1

25X1 25X1

The guidance system at the BAM site consists of a previously unknown multiple screen guidance stater, a SPOON REST radar, 6 ZIS 151 vans and 3 generator trailers. All components of the guidance system, including the missile launchers, are linked by a cable net (fig. 3).	
The guidance radar (fig. 1, 2) consists of a cab stop which are mounted horizontal and vertical probable electronic scan radars, a parabolic dish, a flat or very slightly curved dish, and a long narrow housing of unknown purpose. The entire unit is mounted on a low wheeled carriage. The cab, with the attached antenna array, has been observed on photography to rotate 180° in aximuth. There is no physical obstacle to prevent a 360° rotational capability. All reflectors except the horizontal scanning radar have been observed in elevation train. It should be noted that the elevation train, when observed was present in all these reflectors and apparently in the same amount.	25)
The horizontal and vertical scanning radars, long	25)
respectively, appear to be identical in construction except for the dif- ference in length. The curved reflectors are	05)
feed extending the length of the reflector. The feed emanates from the	25)
side of the reflector, extending almost half way across and leaving a	25>
gap between the tip of the feed and the rear of the screen (fig. 2).	
	25)
The	
vertical reflector, however, has been observed on photography to tilt upward 30°. There is no obstacle to prevent further tilt of the vertical reflector.	
A parabolic dish is mounted on an arm extending from the end of the horizontal reflector supporting structure. No feed is discernible for this dish. The arm and dish have been observed in two positions: with the arm and dish parallel to the long axis of the radar and the dish exiented vertically; with the arm rotated forward 45°, at which time the dish was toed-in 20° and tilted up approximately 30°. There is no apparent physical obstacle to prevent either additional arm motion or tilt of the parabolic dish, however, the lack of any extensive mechanism suggests that the capability for arm motion is limited. The length of the arm, and the absence of any bracing members, suggests that the dish might lack the physical stability necessary to establish fine direction at extended ranges.	
A dish, with a flat or very slightly curved surface, is mounted at the top from of the horizontal scanning radar. The feed for this dish consists of a dismeter cylinder, long, mounted, by means of a smaller diameter rod, from the face of the dish. This dish has been observed, on comparative photographic coverage, both in the vertical position and tith a back tilt of approximately 30°. So eximuth train has been observed. Since the bottom of the dish when in the vertical position slightly overlaps	25)

25X1

25X1

2004/07/08 : CIA-RDP81T00990R000 00020039-9

M50/PIC/107/59

ILLEGIB

25X 25X

the front of the horizontal scanning undar, azimuth train would be obstructed unless sufficient tilt were induced for the bottom of the dish to clear the

horizontal screen.		
housing of unknown purpose. It is height, and is slightly round	izontal radar supporting structure is a measures by approximately ded at the ends. It has been theorised tantennee for missile guidance command.	2 2
in the 6 ZIS 151 vans parked in radar (fig. 3). These 6 trucks only the length of the line of radar, the SPOON REST radar, as cable link. The power source, adjoining revenuent. A seventh	the missile guidance system is loca a the revetment adjacent to the guidance are linked into a heavy cable, which run vehicles. Lighter cables from the guidan and the launchers lead into this central three generator trailers, is located in a ZIS van is parked by the generator trail to the cable net, and may be a maintenance.	ers.
No radar calibration devi-	ce has been identified.	
and HAT RACK antennae, was local		the 2

25X1